


FIBER OPTIC PATCH CABLES




Quick Start Guide


V 2.2

Copyright © 2021 Fibline All Rights Reserved.


1. Product View




LC-Lucent Connector




Standard Clip Lc Uniboot



SC-Subscriber Connector





ST-Straight Tip




FC-Ferrule Connector

2. Clean Connector




2.5mm Pen One-Push Cleaner used to clean SC/ST/FC connectors.


3. Polarity Reversal of LC Uniboot



Open connector top




Switch the polarity A-B to A-A




Close connector top


4. Polarity Reversal of Flat Clip LC UUniboot




Open connector top




Switch the polarity A-B to A-A




Close connector top



Rotate the connector body 180°




Reposition the clip




The polarity is reversed

5. Install the LC Connector into Transceiver Module

LC



Install the LC Connector into Adapter




NOTE:


1. When installing, align the key on the connector body with the keyway on the transceiver or adapter.
2. When removing the LC connector, press the connector latch downward.

6. Install the SC Connector into Transceiver Module


SC



Install the SC Connector into Adapter



7. Install the ST Connector into Adapter

ST**Install the FC Connector into Adapter****FC**